Feet Chains and witnessed as described by the Surveyor General. The true course of line is S.89°47'E. Land; mountainous. Soil; poor 4th rate. Timber; fir, spruce & pine. Dense undergrowth; willow & alder. Mountainous land, heavily timbered & dense undergrowth, 39.99 chs. Aug. 4th, 1903. Retracement S. Bdy., T.4 N., R.38 E., W. M. As surveyed by same U.S. Deputy Surveyor, Under the same Contract & date. Determine true meridian with the Solar at Cor. to Secs. 32 & Post Cor., as described by the Surveyor-General, destroyed by fire & bearing trees, also destroyed. I re-establish in exact location as follows:-Set pine post, 3 ft. long, 4 ins. sq., 24 ins. in ground, for Cor. to Secs. 32 & 33, on S. Bdy. of T.4 N., R. 38 E., marked T.4 N., S.33 on N.E., R.38 E., S.32 on N.W. faces, with 4 notches on E. and 2 notches on W. edges, from which which, A temarack, 8 ins. diam., brs. N.56°W., 30 lks. dist., marked T.4 N., R.38 E., S.32, B.T. A pine, 3 ins. diam., brs. N.46°E., 15 1ks. dist., marked T.4 N., R.38 E., S.33, B.T. Thence I run E. bet. Secs. 5 & 33. 37.57 A point, 73 lks. S. of old Closing Cor. to Secs. 4 & 5, established in 1899. 40.40 The 1 Sec. Cor. on S. Bdy. of Sec. 33, standing in thick clump of bushes & escaped my search. Two fallen trees decayed, original witness trees as described by the Surveyor General. I re-establish this Cor., in original position, as follows: Set fir post, 3 ft. long, 3 ins. sq., 24 ins;, in ground, for \$\frac{1}{4} Sec. Cor. on S. Bdy. of Sec. 33, marked \$\frac{1}{4} S.33 on