OREGON COI JER RESTORATION FORM 10 Township 15 Range 34E 11-04-2004 County Umatilla Date: Condition Report Only Corner Designation: T1SR34EF16 Not Found Remonumented Unrecorded Surveyed In Referenced Out Previous Renewals / Surveys, etc. Umatilla County Survey # 97-173-B Monument and Accessories Found: (condition and source) Corner was found a 5/8" dia. reabar with a 1.25" dia. red (faded pink) plastic cap with ORLS 0852 and WALS 13922 stamped in the center. Found a 5' steel t-post in the ground to the south of the corner. (see attached photographs) SKETCH DIAGRAM N.E. 1/16th of the S.E. 1/4 of the N.E. 1/4 of Section 10. Rebar at the ORLS 0852 S.E. base of a 14" dia. Douglas Fir tree. WALS 13922 Corner bears S 78°21'19"E, 6.77 feet. Rebar at the N.E. base of a 14" Douglas Fir tree/ 1.25" dia.Red plastic cap Corner bears N 27 °43 '35 "E, 27.88 feet MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) Set a Umatilla County Sign on the 5' Steel T-post previously set on the south side of the corner.. (See attached photographs) REFERENCES SET: Set two 5/8"x30" iron rebar with a 1.25" dia. red plastic cap stamped WALS 13922 and ORLS 0852. As shown in sketch above. (See attached photographs) Location and Comments Surveyors Seal Compass Declination From the NC 1/16th corner southwest of the old school and Umatilla County road # 1046 (Ross Road). Proceed east on a bearing of S 89°36'41"E to a distance of 1288 feet along the new posted fence line to the corner REGISTERED line to the corner. PROFESSIONAL LAND SURVEYOR RECEIVED BY: Firm / Agency David L. Haddock Date: 1-05 Rec'd By: KK No. 08-04-8 Haddock Surveying OREGON JULY 12, 1968 ID L. HADDOCK P. O. Box 1574 Pendleton, OR 97801 DAVID L. (541) 276-2174

RENEWS 6-30-05