005000 000000 000000		
OREGON CORNER RESTORATION		
Section <u>26</u> Township	<u>2N</u> Range <u>32 E</u>	
CountyUmatilla	Date 1-16-90	
CORNER DESIGNATION	s, etc. Renewal by	Condition Report Only X Not Found Renewed Unrecorded X Surveyed In X Referenced Out R.P. Thompson, Nov. 1972 set I.P.
monuments to the nor angles and distances	th and set the sec The corner is leads to be probably dest	P. I found two of his tion corner using Thompson ocated 0.9 feet N.W. of royed the stone and I.P.
Monument Detail		Sketch
522 523 527 526 1990 P.L.S. 1330	Wood fence Part *** Wood Fence Part *** Wood Fence Past Wood Fence Past	RR tie 29.7' North post 29.7' North 1500
3. 133		Power Pole
Monument Set (Procedures		
		2½" brass cap 6" above
ground and 0.9 feet]	N.W. from large pov	wer pole.

lew Accessories		
l. Good R.R. tie gat	te post bears north	n 29.7 ft.
3. Good wood fence		
		.8 ft.
All witness posts hav		
ocation & Comments	N98 (1.1774) (1.1765)	Surveyor's Seal
0.9 ft N.W. from	Compass Declination	AND THE PROPERTY OF THE PARTY O
large power pole	Firm/Agency Don St	PROFESSIONAL
MAIN PROPERTY. Units	Engineer - Surve	LAND SURVEYOR
RECEIVED BY	_ Address 1532 S.W.	N "1 0 11 -1
Matilla County Surveyor 1-90	Pendleton, OR 9 Party Chief Don St	aebler OREGON
rider A	Notes	DONALD L. STAEBLER

Witness_