

9-15

OREGON CORNER RESTORATION FORM

Section 10 Township 2 N Range 33E

County Umatilla Date Jan. 1994

9-15

CORNER DESIGNATION



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

Found railroad spike that has been used in the past and was referenced with a hub and tack 55.15 ft. to south and a P-K nail on line approx. another 200' + south. These references were placed before construction started of the new road surface and grade.

Monument Detail



Monument Set (Procedures and Description)

Set 2 1/2" brass cap on 1" x 30" G.I.P. 6" below paved surface in a C.I. monument box with a lid.

New Accessories 1. Set alum. nail in middle of bearing object sign on N. E. face of power pole S.E. 46.35' from the corner.

2. Set alum. nail in middle of bearing object sign on E. face of power pole S. W. 90.55 ft. from the corner.

3. Set alum. nail in middle of bearing object sign on S. face of a 14" diameter locust tree N.W. 94.33 ft. from the corner.

4. Set alum. nail in middle of a bearing object sign on S. face of a 8" diameter locust tree N. E. 149.99 ft. from the corner.

Location & Comments

Corner is in the middle of the paved road. Compass Declination _____ Firm/Agency Don Staebler

RECEIVED BY _____ Address 1532 S. W. 41

Umatilla County Surveyor Pendleton, OR 97801

Date 2-94 Party Chief Don Staebler

Rec'd By gkk Notes _____

No. 94-08-11 Witness _____

Surveyor's Seal



Donald L. Staebler

