CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 2N, R 33E. . .M.

Corner Code No. L-13
Note: Monument marked as shown below

History of original corner establishment:

This corner was last established by C.E. Redfield, U.S. Indian Service Surveyor, during his surveys in the area between 1913 and 1970. Redfield notes the re-established corner to be 0.475 chains South of a fenceline extending East.

DIAGRAM
T2N R33E
1/4 42.5 E
S16 : S15
1993
PLS 1106

Corner No. Compass Declination: 18.0°

Description of corner evidence found:

None. The corner area has been disturbed by sewerline and road construction.

The corner was re-established by single proportion measurement between the re-established Northwest and Southwest Corners of Section 15, using Redfield's record.

Description of monument and accessories I established to perpetuate the original location of this corner:

The corner point falls in a paved highway. At a point N $89^{\circ}38'53"$ E 42.50 feet from the true corner point, I set a 2 1/2" brass cap on a 1 1/4" by 30" galvanized iron pipe 30" in the ground as a witness corner monument. The witness corner monument is referenced as follows:

A 5/8" by 30" iron pin bears N 21° 03'36" E 32.10'.
A 3/4" brass washer nailed to UECA pole no. 169400 bears N 48°31'35" W 102.68'.
A 3/4" brass washer nailed to UECA pole no. 169401 bears S 18°51'33" W 244.38'.
A 3/4" brass washer nailed to PP&L pole no. 150400 bears S 00°02'12" E 129.82'.

Set steel fence post with witness corner sign attached 1.3' East of the witness corner monument.

The 5/8" iron pin is capped with a 1 1/2" yellow plastic cap marked "W.R. Wells, PLS 1106".

Bearing object signs are nailed to each pole near the $3/4^{\circ}$ brass washers. A bearing object sign is wired to the $5/8^{\circ}$ iron pin.

The 3/4" brass washers are stamped "PLS 1106".

PROFESSIONAL
LAND SURVEYOR

Will: R. Wells

OREGON
JULY 22, 1977

WILLIAM R. WELLS

1106

EXPIRES 12-31-94

REGISTERED

Form R6-7100-57 (9/71)

₩ GPO-798-276