PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/28/02

CORNER DESIGNATION: 2N33L21, The East 1/4 corner of Section 14.

PREVIOUS RENEWALS/ SURVEYS, ETC ..:

Most recent Umatilla County Surveyors recorded survey record: 93-53-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 5/8" x 30" iron rebar with cap burned off East 1/4 corner of Section 14. No visible accessories.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

Corner at railroad tie fence corner post, fences running South and East.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 729632.55E = 8677047.02

FIRM/AGENCY: W

William R. Wells

P.O. Box 1696

Pendleton, Oregon 97801

\2N33L21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON JULY 22, 1977 WILLIAM R. WELLS

1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 05-02

Rec'd By

Na 02-115-9