OREGON CORNER RESTORATION FORM 36 Range 34E Township 11-28-01 County Umatilla Date: Corner Designation: 2S34Z25 Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out Previous Renewals / Surveys, etc. Barry Barbour, PLS 1051, remonumented this corner in 1980. He found the original stone; a 19" dead pine N74°E, 47.9', with scribing; a 16" pine, S40°E, 33.9', with scribing; a 24" pine, S15°W, 37.3', with healed blaze; and a stump N50°W, 198.2'. At the center of the stone, he set a 2 1/2" x 30" galvanized iron pipe with brass cap marked as shown in the diagarm. He set two new bearing trees as follows: a 14" pine bears N59°E, 86.3' scribed T2SR35ES31BT; a 12" pine beras N75°W, 29.3' scribed T2SR34ES36BT. Monument and Accessories Found: (condition and source) Found the corner as described by Barbour. The monument was in good shape. The bearing trees were unchanged. BT stump 0 north - south CIAGRAM fence SKETCH T2S **▲**BT R35E R34E _dead BT corner S36 | S31 BT B 51 **S5** T3S ORPLS 1051 1980 MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None. REFERENCES SET: None. Made GPS tie to TRI Station GRIEFY. Oregon State Plane Coord. - North Zone Latitude 45 *20 '24.49417"N Northing 616530.13 Longitude 118 *29 '23.89477"W Easting 8718870.72 NAD 83 (1991) Ortho Height 4550.03 Ellipsoidal Height 4491.62 Location and Comments Compass Declination Surveyors Seal Form Pilot Rock, go east on Birch Creek Road to a point 4 miles beyond Indian Lake 50 .E to a cattle guard crossing. From this point follow the REGISTERED PROFESSIONAL fence 1/4 mile south to the LAND SURVEYOR corner. RECEIVED BY: David L. Has Firm / Agency Haddock Surveying P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174 OREGON 01-02 Rec'd By

12, 1968 HADDOCK

RENEWS 6-30-03

DAVID L

By: KK