OREGON CORNER RE	STORATION FO	)RM
Section 20 Townsh County Umatilla Date:		Range 28E
Corner Designation: 3N28P5		Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out
Previous Renewals / Surveys.		
Oregon Carner Restaration For	rm by David Haddock da	ted 1-31-2000.
Newbill records a rock at thi	s location in 1954 und	der survey Q-506-A.
Monument and Accessories Four	nd: ( condition and so	urce )
		250 G
An existing east west fence.		10
	SKETCH	# #
DIAGRAM	iran rebar under fence NB3 31'22"W, 49.47	iron rebar feace under feace N83 17 08 E, 34.42
S19 S20 2000 PLS 852	iron rebar COF at base of pp S87*41'13"W 138.03'	at base of property of the part of property of the part of the par
MONUMENT (S) AND ACCESSORIES	SET (Procedures and De	escription)
None.		1 / /
REFERENCES SET:		
None. Made GPS tie to TRI Station Stanfield East Base. Latitude 45 43 34.77463 N Longitude 119 21 08.00027 W NAD 83 (1991)	Northing	ane Coord North Zone 752991.56 8495209.24 691.14 ght 621.47
Location and Comments	Compass Declination 20°E	Surveyors Seal
From the junction of Highways north 1.1 mile. Turn west ont go 0.1 mile. The corner is alothe south.	n a side road and	REGISTERED PROFESSIONAL LAND SURVEYOR
RECEIVED BY:	Firm / Agency	David L. Haddock
Date: 12-02 Rec'd By: KK No. 02-283-9	Haddock Surveying P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174	OREGON JULY 12, 1968 DAVID L. HADDOCK 852
	12-12/ E/O E1/4	RENEWS 6-30-03