

OREGON CORNER RESTORATION FORM

Section 30 Township 3N Range 28E
 County Umatilla Date: 06-14-02

Corner Designation: 3N28V1


Condition Report Only
 Not Found
 Remonumented
 Unrecorded
 Surveyed In
 Referenced Out

Previous Renewals / Surveys, etc.

Survey H-107-B records finding a brass cap here and setting a spike.
 Survey L-36-A found a spike. Survey 82-41-Ax found a brass cap and a
 brass capped witness corner. Survey 90-52-A set a brass cap here.
 Survey 95-175-B found a brass cap here.

Monument and Accessories Found: (condition and source)

Found a brass capped monument stamped as shown on the drawing in good condition 6" below the surface of the road.



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.

Made GPS tie to TRI Station Stanfield East Base.	Oregon State Plane Coord. - North Zone
Latitude 45°42'43.02996" N	Northing 747677.94
Longitude 119°22'21.19518" W	Easting 8492090.53
NAD 83 (1991)	Ortho Height 729.95
	Ellipsoidal Height 660.34

Location and Comments

Compass Declination
20°E

Surveyors Seal

From the junction of Highway 207 and Saylor Road, go north 1.0 mile. Monument is in road at this point.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

RECEIVED BY:

Firm / Agency

David L. Haddock

Date: 7-02
 Rec'd By: DK
 No. 02-187-9

Haddock Surveying
 P. O. Box 1574
 Pendleton, OR 97801
 (541) 276-2174

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852