OREGON CORNER RESTORATION FORM						
Section	6,7	Township	3N	Range	29E	
County	Umatilla	Date:	01/10/09			
Corner Designation: 3N29E3						
1/4 Corne	er common to sections	6 and 7, T3N	R29E	-	x	Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out
Previous Renewals / Surveys, etc. Originally Surveyed by Gates in 1859. He set a post in a mound of earth. In 2001 Haddock found a 1 1/2" steel shaft.						
Monuments and Accessories Found: (Condition and Source) A 1 1/2" steel shaft.						
	laaram			1		
	iagram		Brass washer Railroad tie fence pos N 25°45' W 52.18'	st teel shaft	Sketch	5/8" Iron Rebar w/ypc N 34°45' W * 54.60'
			Brass washer Railroad tie fence pos S 75°00' W 18.27'	st		5/8" Iron rebar w/ypc S 41°45' E 27.66'
NAD 83/91 OREGON STATE PLANE NORTH INTERNATIONAL FEET						
N766541.49 E8524689.81						
LAT - 45° 45' 44.19300" N LON - 119° 14' 09.48554" W						
Monument (s) Set (Procedures and Description)						
None.						
References Set:  A brass washer #43406 and nail on a railroad tie fence post lies N 25°45' W, 52.18'.  A 5/8" x 30" Iron rebar w/ypc lies N 34°45' E, 54.60'.  A 5/8" x 30" Iron rebar w/ypc lies S 41°45' E, 27.66'.  A brass washer #43406 and nail on a railroad tie fence post lies S 75°00' W, 18.27'.						
	and Comments ntersection of Echo M		Compass Declination	1	Surve	yors Seal
	matilla Meadows Rd.		17° E		PROF	ISTERED ESSIONAL SURVEYOR
RECE	IVED BY:		Firm / Agency	1	Post of a	201
Date: _ Rec'd No	1-15 By:	-	Survey One, LLC. P.O. Box 382 Pendleton, OR 97 (541) 276-2055		JANU ROBERT DO	REGOM NARY II, 2005 DUGLAS ENGLISH 3406LS