N PUBLIC LAND CORNER REPORT / RESTORATION REPORT / Umatilla County Surveyor's Office

SECTION	TOWNSHIP		RANG	E	
18	3N 36E		100000000000000000000000000000000000000		
COUNTY: Umatilla				DATE 6/20/08	
CORNER DESIGNATION: M-4				(Please check one)	
South 1/16 corner common to sections 17 and 18			Ø	Condition Report Only	
Country Connect Committee Co	o occiono 17 ana 10		- 1		Not Found
			- 1	무	Renewed
			- 1		Unrecorded Surveyed In
				Referenced Out	
Previous Renewals / Surveys, etc.					
U.S. Indian Services Surveyor C.E. Redfield, set a 2" X 36" Galvanized Iron Pipe with a 2 1/2" Brass Cap attached in September 1919. See Redfield notes Page 238.					
Monument(s) & Accessories Found: (Condition & Source)					
Found a 2" Galvanized Iron Pipe with a 2 ½" Brass Cap, protruding 10" at a Fence Corner, 1 foot South of a power					
pole and 0.7 feet Southeast of a Railroad Tie Fence Corner Post					
Monument Detail:		Sketch:			
INDIAN ALLOTMENT					
POWER POLE					
/ 1/16				-x-)"x /
RRTIE POST				10	
C S18					E MONUMENT
\ G -S18 /			,	ķ	
\				-	1 1
T3N R 36E			10	×	
					ΝÍ
Monument Set (Procedures and Description):					
Monument Set (Procedures and Description).					
\$					
New Accessories:					
NONE					
Location & Comments:				Co	mpass Declination:
Monument is located on flat open ridge at a Fence Corner 200 feet ±					
South of County Road No. 872	en nage at a Fence Come	200 16613		1	1
County Node No. 012					
Firm / Agency				S	URVEYOR'S SEAL
USKH Address: 5 N. Colville St., Walla Walla, Wa 99632					
Tital Soci of the Social Socia					
Party Chief				_	PECIOTERED
Greg E. Flowers				(REGISTERED PROFESSIONAL
Notes				L	LAND SURVEYOR
-020 Q-000 Q-00				1	reg E. Fluters
Witness				~	OREGON
Damon Locke					JUNE 30, 1997 GREG E. FLOWERS
					02820LS
				100	RENEWS /2 / 31 /09
		^-	ant news		6/30/08
		/11/ //	2		40 BECK

. 08-112-c