CORVED DEGMODATION	FORM					
OREGON CORNER RESTORATION	FORM					
Section 32 Townshi	p 4N	Range	29E	Index	X6	
County Umatilla Date	5/05/95					
			03!4	ion Dononi	0.01.	
CORNER DESIGNATION		Condition Report Only Not Found				
CW1/16			Renewe			
		Unrecorded				
		x	Survey Refere			
			Kerere	nce		
Previous Renewals/Surveys	, etc					
Monument(s) & Accessories	Found:	(Condit	ion and	Source)		
Found 5/8 " steel rebar.	1/2 " iro	n pin rec	orded in	Umatilla	County	
Public Monumentation Surv	rey 1994-1	by Edwar	ds.			
Warrant Datail			Sketch			
Monument Detail			Ske tell			
Monument Set (Procedures	and Descr	eintion)				
Mondment Det (11000da105						
New Accessories						
Tied to existing features						
Chain link fence post to	bus barn	bears S76	°56'W, 3	0.7'.		
Chain link fence post to	bus barn	bears N65	32'W, 3	3.1'.		
Galvanized pipe street s	ign bears	N79°07'E,	133.1'.			
Galvanized pipe street s	ign bears	S78 25 E	147.4'.			
Location & Comments	_				or's Seal	
In Stanfield, go to the Compass Declination_20°					GISTERED	
west end of Harding Ave. at the school bus barn	Firm/Agency Haddock Surveying			PRO	LAND SURVEYOR	
gate.	Address	Address_P. Box 1574				
gate.	Pendlet	Pendleton, OR 97801			4. Haddock	
	Party Chief D. Haddock					
	Notes				SHEGON .	
		s_S. Hado	1 - 1		DREGON ULY 12 1966 L. HADDOCK	

RECEIVED BY

Umatilla County Survey
Date 6-95
Reo'd By KK
No. 95-103-R