OREGON CORNER RESTORATION FORM SECTION:33 TOWNSHIP: 5N RANGE: 29E V-13 COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED NE Section 33 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1971 Thompson set a 2 1/2" brass cap. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE

Found 5/8" iron rebar 4" below the surface of a paved road.

W.C. a 2 1/2" brass cap stamped as below bears N 45° 11' 57" W 46.58' (46.66')

MONUMENT DETAIL

T5NR29E _28 | 27 33 | 34 N45W 46.66 1971

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

809243.53 8537704.37

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 5° 51' 49" E 183.91' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 33° 31' 25" E 31.20' A 5/8 x 30" Iron Rebar with plastic cap #951 bears S 16° 44' 05" W 62.34'

LOCATION AND COMMENTS

At the intersection of Tabor road and Walls road.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/05

c:\Works\Restform\L_5

06-265-C