OREGON CORNER RESTORATION FORM SECTION:35 TOWNSHIP: 5N RANGE: 29E X-21 **DATE: 12/05 COUNTY: UMATILLA** CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED E1/4 Section 35 UNRECORDED X SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Nothing found MONUMENT DETAIL T5NR29E 1/4 35 36 2005 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 806762.03 8548308.22

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1" x30" iron pipe in concrete with a 2 3/8" brass cap stamped as above 2" above the ground.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 62° 41' 09" W 135.21'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 17° 41' 03" W 322.73'
A 5/8 x 30 Iron Rebar with plastic cap #951 bears N 6° 36' 53" W 1407.51'
1/16 corner 5/8"x30" Iron Rebar with plastic cap #1106 bears N 0° 15' 00" W 1325.90'

LOCATION AND COMMENTS

Corner falls into the trees of Cold Springs Reservoir about 350' from the North edge of the trees.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L_5

06-265-C