OREGON CORNER RESTORATION		
Section 19 Townshi County Umatilla Date:	p 5N 01/15/10	Range 35E
Corner Designation: 5N35N3		
Corner common to sections 18,19 T5NR3	5E	Condition Report Only  X Not Found Remonumented Unrecorded X Surveyed In X Referenced Out
Previous Renewals / Surveys, etc.		
Monuments and Accessories Found: (C None.	Condition and Source)	
Diagram  T5N R35E		Sketch
1/4 S18 S19 PLS43406LS 2009		2• 3/8••BC ↓
NAD 83/91 OREGON STATE PLANE NORTH INTERNATIONAL FEET		• • •
N822172.98 E8714772.29 LAT - 45° 54' 15.244777" N LON - 118° 29' 09.490902" W		<b>†</b>
Monument (s) Set (Procedures and Des Set a 1 ½" Galvanized Iron pipe w/ a 2 ½" A ½"x30" Iron rebar w/ypc #43406 lies N 3 A ½"x30" Iron rebar w/ypc #43406 lies N 5 A ½"x30" Iron rebar w/ypc #43406 lies S 3 A ½"x30" Iron rebar w/ypc #43406 lies S 6	Brass Cap Stamped as 35° W, 11.82'. 55° E, 12.61'. 99°30' E, 13.90'.	shown.
References Set: None Location and Comments		
Cor. approx. 30' W of N-S fence on Easterly facing slope above Pine Creek.	Compass Declination 17° E	REGISTERED PROFESSIONAL LAND SURVEYOR
RECEIVED BY:	Firm / Agency Survey One, LLC	Prof. D. Eyled  JANUARY II, 2005  DOBERT DOLLAR ENGLISH
Date:/2 ~69 Rec'd By: No09~176~2	P.O. Box 382 Pendleton, OR 9 (541) 276-2055	7801 RENEWAL DATE: 12/31/II

Γ