OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 9/24/2014

CORNER DESIGNATION: R-11, Section Quarter Corner common to Sections 21, and 28 Township 6 North, Range 37 East, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by George Williams, Contract No. 176, dated July 20, 1872. His notes state "Set post & marked stone mound & pits for 1/4 sec cor."

MOUNUMENT AND ACCESSORIES FOUND:

No evidence found.

MOUNUMENT MARKING DETAIL:

T₆N

LS 02820

S 21

S 28

R37E

12/2014

MOUNUMENT AND ACCESSORIES SET:

At the surveyed position, set a 2½" brass cap on 1½" galvanized iron pipe, 6" above ground from which set:

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N55°W, 15.00 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears N66°E, 15.00 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S44°E, 15.00 feet distance.

A 5/8" x 30" iron rebar with yellow plastic cap "TLS-HDJ" bears S47°W, 15.00 feet distance.

LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 850696.48

E = 8788054.28

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM: HDJ Design Group

5 N. Colville, Suite 200

Walla Walla WA 99362

WITNESSES: Joseph R. Latimer

Cory A. West

OREGON
JUNE 30, 1997
GREG E. FLOWERS

REGISTERED PROFESSIONAL

LAND SURVEYOR

02820LS RENEWS 12/31/15

06/29/2015