OREGON CORNER RESTORATION FORM

COUNTY: Umatilla DATE: 6/24/2014

CORNER DESIGNATION:

Z-5, Section Corner common to Sections 31 and 32 Township 6 North, Range 37 East and Sections 6 and 5, Township 5 North, Range 37E, W.M.

PREVIOUS RENEWALS/SURVEYS ETC:

Originally surveyed by William H. Odell and William S. Lewis, Deputy Surveyors, Contract No. 110, dated February 7, 1865. Their notes state "Set post for Sections 31, 32, 5 & 6 on a side hill facing the west, deposited marked stone, dug pits and raised mound as per instructions."

MOUNUMENT AND ACCESSORIES FOUND:

Found well established old fence corner with fences running east, west, and south and a line of ancient rock jacks running N. 20° E., from the fence corner. I accepted this as the best evidence of the corner location.

MOUNUMENT MARKING DETAIL:

S31 S32 T6N S6 S5 R37E 2014 T5N LS 02820

MOUNUMENT AND ACCESSORIES SET:

At the fence intersection, set a 1½" x 30" galvanized iron pipe with a 2½" brass cap stamped as Corner common to Sections 31 and 32 Township 6 North, Range 37 East and Sections 6 and 5, Township 5 North, Range 37E from which:

Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N76°W, 28.60 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears N34°E, 15.45 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S10°E, 18.90 feet. Set a 5/8" iron rebar with yellow plastic cap marked "TLS-HDJ" bears S14°W, 25.90 feet.

LOCATION AND COMMENTS:

Bearings taken with Silva hand compass and distances measured with a steel tape.

OREGON STATE PLANE COORDINATE, North Zone, NAD 83(91), International Feet:

N = 839993.68E = 8780572.53

COMPASS DECLINATION: 15° East

SURVEYORS' SEAL:

FIRM: HDJ Design Group
5 N. Colville, Suite 200
Walla Walla WA 99362

WITNESSES: Thomas J. Boshart Felipe G. Hernandez

OREGON
JUNE 30, 1997
GREG E. FLOWERS

REGISTERED PROFESSIONAL

LAND SURVEYOR

RENEWS 12/31/15 06/29/20/5