Chains Feet General Description. This Tp. is rolling in the South portion, very rough and mountainous in the North. Good pine and tamarack timber, also good bunch grass. Soil, 1st & 4th rate. That portion of the Tp. not subdivided is a nest of impassable canyons, making it impossible to survey the same within limits allowed, and the lands are comparatively worthless. The timber in this Sec. is poor and scattering and of no value on account of its inaccessibility. Resurvey Portion East Bdy., T. 2 S., R.34 E., W.M. As surveyed by L.E. Wilkes, U.S. Depy. Surveyor, Under Special Instructs Dated Feb., 20, 1917. Retracements. From the Cor. of Secs. 13, 18, 19 & 24, on the E. Bdy. of the Tp., N. retracing the line bet. Secs. 13 & 18, at 40.23 chs. pass 13 lks. W. of the 4 Sec. Cor., and at 80.40 chs., fall 13 lks. W. of the Cor. of Secs. 7, 12, 13 & 18. N. retracing the line bet. Secs. 7 & 12, at 40.29 chs. fall 19 lks. W. of the 2 Sec. Cor. This half mile being out of limits and the line subject to rectification, I continue my measurements, setting temp. Cors., and at 2 miles, 82 lks. fall 19 lks. W. of the Cor. of Tps. 1 & 2 S., Rs.34 & 35 E. I commence at the Cor. of Secs. 13, 18, 19 & 24, on the E. Bdy. of the Tp., which is a volcanic stone, 5 x 3 x 1 ft. above ground, not marked. At the exact Cor. point as determined by the original bearing trees, cut a cross (X)

for Cor. of Secs. 13, 18, 19 & 24, marked with 3 notches

A tamarack, 12 ins. diam., brs. N.85°E.,

N. & S. of cross; from which,