Subdivisional Lines of Township 3 North, Range 36 E. W.	. M.	1.	W.	E.	36	Range	North.	3	Township	of	Lines	Subdivisional
---	------	----	----	----	----	-------	--------	---	----------	----	-------	---------------

L SS , LIST MINE

3

Subdivisiona; Lines of Township 3 North, Range 36 E. W. M.	•
to See 14 15 99 and 97 7	
99-0, 30	
81	
willow and other underbrush. Good grass.	
Oct. 5th 1878.	
East on a random line between Sec. 14 and 23.	
Va. 20° 30' East.	
Set post for temporary ½ sec. cor.	
Intersected N. and S. line, 58 lks. North of cor. to	
Sec. 13, 14, 23 and 24 from which cor. I run	
N.89°35' West on a true line between Sec. 14 and 23.	
Va. 18°45' East.	
Ravine, course South.	
Set stone, 20x12x4 on East hillside for 2 sec. cor.	<b>ļ</b> 5
The cor. to Sec. 14, 15, 22 and 23.	
Land: surface very broken and mountainous. Soil, 3rd	
rate. No timber; good grass.	
Sec. 23 has some 1st rate soil on river bottom. Bottom	
is from 3 to 8 chs. wide and is mostly covered with	
good timber. All South of river has more or less tim-	
ber.	
North between Sec. 14 and 15.	
Va. 20° 30! East.	
Set stone 20x12x5 on West hillsade for 4 sec. cor.	<del> </del> 9
Enter timber, course E. & W.	
Set fir post for cor. to Sec. 10, 11, 14 & 15, from	10
which a	e
A fir, 8 in diem. brs. N.10° E.70 lks. dist.	
A fir, 10 in diam, brs./S. 42° E. 40 lks. dist.	
A fir, 8 in diem. brs. S. 28° W. 27 lks. dist.	
Good timber on N. 30 chs. Pine, fir and tamarack.	
	to Sec. 14, 15, 22 and 23. Drove stake and raised mound of stone around stone and stake in lieu of pits. Land: Surface, mountainous. Soil, 3rd rate, some, 1st rate on river bottom. Some good timber South of and in river bottom. Pine, fir, tamarack and balm; some willow and other underbrush. Good grass.  Oct. 5th 1878.  East on a random line between Sec. 14 and 23.  Va. 20° 30' East.  Set post for temporary \$\frac{1}{2}\$ sec. cor.  Intersected N. and S. 1ane, 58 lks. North of cor. to \$\frac{1}{2}\$ gec. 15, 14, 23 and 24 from which cor. I run N.89°35' West on a true line between Sec. 14 and 23.  Va. 18°45' East.  Ravine, course South.  Set stone, 20x12x4 on East hillside for \$\frac{1}{2}\$ sec. cor.  The cor. to Sec. 14, 15, 22 and 23.  Land: surface very broken and mountainous. Soil, 3rd rate. No timber; good grass.  Sec. 23 has some lst rate soil on river bottom. Bottom is from 3 to 8 chs. wide and is mostly covered with good timber. Whi South of river has more or less timber.  North between Sec. 14 and 15.  Va. 20° 30' East.  Set stone 20x12x5 on West hillside for \$\frac{1}{2}\$ sec. cor.  Enter timber, course E. & W.  Set fir post for cor. to Sec. 10, 11, 14 & 15, from which a  A fir, 8 in qiam. brs. N.10° E.70 lks. dist.  A fir, 8 in diam. brs. S. 28° W. 27 lks. dist.  A fir, 8 in diam. brs. S. 28° W. 27 lks. dist.  A fir, 8 in diam. brs. N. 70° W. 22 lks. dist.  Land; Surface, mountainous. Soil, 3rd, 2nd and 1st rate.