OREGON CORNER RESTORATION FORM

Section 30 Township 1 N Range 37 E.

County Umatilla Date Sept., 1993

CORNER DESIGNATION

south 1/16 80 chains, section 30
corner index: U-1/2

_____ Condition Report Only
_____ Not Found
_____ Renewed
_____ Unrecorded
__X__ Surveyed In
_____ Referenced Out

Previous Renewals/Surveys, etc.

There is no record of any surveys in this area.

Monument(s) & Accessories Found: (Condition and Source)

No monument was found in this area.

Monument Detail

Sketch

Monument Set (Procedures and Description)

At a section subdivision as determined by this survey I set a 3-1/4" aluminum cap on a 2-1/2"x 30" aluminum pipe, 24" in the ground, with a land survey monument and property boundary signs attached to a steel post nearby.

New Accessories

11" douglas fir bears N.41-1/2°W., 50.5 feet scribed S1/1680S30BT.
1-1/2" aluminum cap (PLS 2535) on a 5/8"x 24"rebar bears N.29-1/2°E., 9.2 ft, cap is stamped 9.2 RM with an arrow pointing toward the corner.

I painted a 6" red band around the bearing tree and attached a bearing tree sign on the front with a land survey monument sign on the back. I attached a brass washer "PLS 2535" in the BT portion of the blaze.

Location & Comments

Compass Declination 18° east
Firm/Agency: White Shield, Inc
Address: P.O. Box 477,
Grandview, WA 98930
Party Chief: Dennis Hartmans
Notes field bk. 3, pg. 13
Witness Wes Cochran

RECEIVED BY
Umatilla County Surveyor
Date 12-93
Rec'd By KC
No. 92-93-B

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Michael P. LeJeune

OREGON 11/4/93
JAN. 21, 1992
MICHAEL P. LE JEUNE
2535

expires Dec. 31, 1994