R-23

REPORT ON CONDITION OF FOUND GOVERNMENT CORNER

Robert Butler | **December 11, 1996** | **Umatilla County**

Description of Corner as Set:

This monument was perpetuated by Lawrence D. Holmes, BLM Cadastral Surveyor under special instructions dated September 22, 1983, Group No. 1184, Oregon. The monument was re-established at record bearing and distance from the original bearing tree. The field notes state:



Set an iron post, 30 ins. long, 2½ ins. diameter, with magnetic, plastic breakaway, 6 ins. in the ground, to solid rock, supported in a mound of stone, 4 ft. base, to top, with a brass cap marked:

T1S R35E
¼ S 24
S 25
1984

from which a new bearing tree

A ponderosa pine, 9 ins. diameter, bears N. 35° W., 160 LKS distance marked ¼ S 24 BT.

Description of Corner Evidence Found:

Found 3" brass cap set in 4' diameter. collar of stone with fence post set in 3' mound of stone to north in good condition.



From which:

A 24" ponderosa pine bears S45°W, 50' distance, with healed over blaze.

An 11" ponderosa pine bears N35°W, 160 LKS, with partially healed blaze.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert E. Butler

OREGON
JULY 25, 1995
ROBERT E. BUTLER
2733

RECEIVED BY
Umatilla County Surveyor
Date 12-96
Rec'd By RK
No. 96-194-B

Expires 12/31/97
Oregon Dept. of Transportation
3012 Island Avenue
La Grande, OR 97850

R-23