G-5

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

SUBMITTED BY CITY ENGINEERING DEPARTMENT PENDLETON, OREGON
CITY ENGINEER James L Chaffee

History of original corner establishment



A 5/8" iron rod was set for the 1/4 corner and has been accepted for many years as being the 1/4 corner between sections 7 and 8 T2N R32E. The rod is shown on many of the surveys done in the area.

Description of corner evidence found:

A 5/8" Iron rod was found in a North-South fence line.

Description of monument and accessories I established to perpetuate the original location of this corner

The 5/8" Iron rod was referenced and removed. A Brass cap mounted on an iron pipe was then set in concrete for the new monument.
The brass cap is stamped " umatilla county surveyor 1/4 /8"
The cross in the center was set for true position from the references.



Office of COUNTY SURVEYOR County of UMATILLA
State of OREGON, I hereby certify that the within instrument was filed in this office for record on the 16 day of MARCH, 1970, at ..... o'clock ..... m., (signed)
Ralph Thompson by .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/66)

G-307