OREGON CORNER RESTORATION FORM

Section 3 Township 3N Range 27E
County Umatilla Date: 06-14-02

Corner Designation: 3N27A15

x	Condition Report Only
	Not Found
	Remonumented
	Unrecorded
X	Surveyed In
	Referenced Out

Previous Renewals / Surveys, etc.

Corner set by GLO in 1940.

Monument and Accessories Found: (condition and source)

Found standard GLO brass cap on 1" iron pipe in intersection of Col. Jordan and County Line Roads. Corner is 3" below surface and has been bent to south.

SKETCH



DIAGRAM



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.
Made GPS tie to TRI Station
Stanfield East Base.
Latitude 45°46'39.17869"N
Longitude 119°25'28.15141"W
NAD 83(1991)

Oregon State Plane Coord. - North Zone	
Northing	771413.77
Easting	8476507.53
Ortho Height	574.49
Ellipsoidal Height	504.53

Location and Comments

This corner may be reached by walking eastward under the power line from the junction of County Line Road and Key Road 0.5 mile.

Compass Declination
20°E

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-03

RECEIVED BY:

Date: 7-02
Rec'd By: KE
No. 02-186-9

Firm / Agency

Haddock Surveying
P. O. Box 1574
Pendleton, OR 97801
(541) 276-2174