OREGON CORNER RESTORATION FORM

Section 2 Township 3N Range 27E
County Umatilla Date: 06-14-02

Corner Designation: 3N27A21

x	Condition Report Only
	Not Found
	Remonumented
	Unrecorded
	Surveyed In
	Referenced Out

Previous Renewals / Surveys, etc.

Corner set by GLO in 1940.

This corner was reported in survey 97-176-B.

Monument and Accessories Found: (condition and source)

Found corner in good condition.

DIAGRAM



SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)

None.

REFERENCES SET:

None.

Made GPS tie to TRI Station
Stanfield East Base.
Latitude 45°46'39.17194"N
Longitude 119°23'35.84588"W
NAD 83(1991)

Oregon State Plane Coord. - North Zone	
Northing	771528.58
Easting	8484466.43
Ortho Height	558.06
Ellipsoidal Height	488.13

Location and Comments

From the quarter corner in the center of the road at 76544 Col. Jordan Road, follow the fence north 0.5 mile to the corner.

Compass Declination
20°E

Surveyors Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

RENEWS 6-30-03

RECEIVED BY:

Date: 7-02
Rec'd By: KK
No. 02-186-9

Firm / Agency

Haddock Surveying
P. O. Box 1574
Pendleton, OR 97801
(541) 276-2174