

City Planning Supervision Valuation Surveying Reports Designs

C. H. Storms & Associates

Phone 2982-M
GEO. LAUBACK
B. F. CHAPMAN
J. O. BICKFORD, Jr.
E. BUCKNER

C. H. STORMS Phone 4692-W

G. M. NEWBILL

CONSULTING ENGINEERS
REGISTERED WASHINGTON, OREGON

TELEPHONE 4170 304 Denny Building WALLA WALLA, WASH.

FILE

Field Notes Section 1-4N R28E

OWNERS

Mr. Ervin Allen Mr. Lester Dungan Mr. Harry Westfall

Having found iron pipes and rock which mark the center of Section 1 4N M28E, the \mathbb{E}^1_4 corner and \mathbb{S}^1_4 corner and South East corner of Section 1. I ran \mathbb{S}^8_9 30 E from the \mathbb{S}^1_4 corner on true line and at mid points, between said $\frac{1}{4}$ corner and rock on S.E. corner of said Section, set stake.

From the 3/4" rod at the E_4^1 corner I ran N89°16'W on true line between said E_4^1 and $1\frac{1}{2}$ "iron pape at the center of said Section 1. At $\frac{1}{4}$ the distance I found 1" iron pipe at $\frac{1}{2}$ the distance set 5/8" iron rod for 1/16 corner.

Then using our control points I proceeded to set property corners in the S.E. $\frac{1}{4}$ of said Section 1, as shown on these accompanying plats.

g.M. Merdill "255"