

WITH TAMALEE BROWN'S WARRANTY DEED INST. NO. 211866 AND I FIND NO OVERLAPS OR GAPS ADJOINING WARRANTY DEED INST. NO. 179172, WARR. WITH ANY OF SAID DEEDS.

THE NORTHWEST CORNER OF SECTION 21 AND THE W1/4 OF SECTION 21 HAVE DUAL RECORD MONUMENTS AT BOTH LOCATIONS. THE MONUMENTS USED IN THIS SURVEY AGREE WITH THE SECTION BREAKDOWN IN THE NW1/4 AS SHOWN ON RECORD OF SURVEY NO. 10-64-B I HELD THE 1-1/2" IRON PIPE AT THE SECTION CORNER AND THE ALUMINUM MONUMENT AT THE W1/4, BY HOLDING THESE MONUMENTS THE USAGE LINES IN THE AREA OF THIS SURVEY FIT IN HARMONY. I CONSIDER THESE MONUMENTS TO BE LOCAL MONUMENTS AND APPLY THEM TO THE NW1/4 OF SECTION 21 ONLY, NO WORK WAS PREFORMED TO CHECK THEIR LOCATIONS WITH ADJACENT SECTIONS, IT MAY BE APPROPRIATE TO USE OTHER LOCAL MONUMENTS WHILE SURVEYING ADJACENT SECTIONS.

THE N1/16 CORNER FOR SECTION 21 WAS ESTABLISHED AND MONUMENTED AT A PROPORTIONATE DISTANCE AND ON LINE BETWEEN THE ACCEPTED ALUMINUM W1/4 MONUMENT AND THE 1-1/2" IRON PIPE SECTION CORNER AND REPRESENTS THE N1/16 FOR SECTION 21 ONLY, NO WORK WAS PREFORMED TO CHECK ITS LOCATION WITH THE ADJACENT SECTION. A MANGLED SPIKE NAIL WAS FOUND 3.7 FEET TO THE SOUTH, SOURCE UNKNOWN.

THE W1/16 CORNER FOR SECTION 21 WAS ESTABLISHED BUT NOT MONUMENTED BECAUSE IT FALLS IN THE RIVER AT A PROPORTIONATE DISTANCE AND ON LINE BETWEEN THE BRASS CAP N1/4 MONUMENT AND THE 1-1/2" IRON PIPE SECTION CORNER AND REPRESENTS THE W1/16 FOR SECTION 21 ONLY, NO WORK WAS PREFORMED TO CHECK ITS LOCATION WITH THE ADJACENT SECTION.

THE CN1/16 CORNER WAS ESTABLISHED AND MONUMENTED AT A PROPORTIONATE DISTANCE AND ON LINE BETWEEN THE BRASS CAP N1/4 MONUMENT AND THE 1/2" REBAR C1/4. A MANGLED SPIKE NAIL WAS FOUND 3.1 FEET TO THE EAST, SOURCE UNKNOWN. IN SURVEY Q941-AX BY EDWARDS SURVEYING AN IRON ROD WAS FOUND. IN RECORD OF SURVEY 12-007B BY EDWARDS SURVEYING THE CN1/16 WAS ESTABLISHED BUT NOT SET A 5/8" REBAR AND CAP WAS SET BY MR. EDWARDS 25' EAST OF THE CN1/16 AS A PROPERTY CORNER, THIS PROPERTY CORNER FITS MY ESTABLISHED AND MONUMENTED CN1/16.


ALL OTHER MONUMENTS WERE FOUND OR SET AS INDICATED IN THE LEGEND AND SHOWN ON THE MAP.

THE FENCE LINE ALONG THE SOUTH BOUNDARY OF THIS PARCEL WONDERS RANDOMLY AND JOGS FURTHEST TO THE SOUTH AT THE SOUTHEAST CORNER DUE TO EXISTING TREES. THE FENCE LINE ALONG THE EAST BOUNDARY OF THE PARCEL RUNS MOSTLY STRAIGHT BUT JOGS TO THE WEST AT THE SOUTHEAST CORNER DUE TO EXISTING TREES. THE REMAINING USAGE LINES AND FENCE LINES FIT WELL WITH THE PROPERTY LINE AS SHOWN.

I, LANCE C KING, A REGISTERED PROFESSIONAL LAND SURVEYOR HEREBY CERTIFY THAT THE FIRST MONUMENT ESTABLISHING OR REESTABLISHING A BOUNDARY MONUMENT WAS PLACED ON 7/17/2013, THAT THE ADJOING PROPERTY AND ALL PROPERTY ACCESSED IN THIS SURVEY WAS DONE IN ACCORDANCE WITH ORS 672.047, THAT THE SURVEY WAS MADE BY ME, OR UNDER MY DIRECTION, THAT THE MONUMENTS ARE AS SHOWN AND THAT THIS MAP IS A TRUE AND ACCURATE REPRESENTATION OF SAID

REFERENCE TABLE

(R1) RECORD OF SURVEY FOR LOUIS WEBB SURVEY NO.10-64-B (R2) RECORD OF SURVEY FOR STEVE & TERRI VOORHEES SURVEY NO. 96-169-B. (R3) RECORD OF SURVEY FOR DALE EVELAND SURVEY NO. 12-007B



TAMALEE BROWN



CK3, LLC

CIVIL-STRUCTURAL-ELECTRICAL ENGINEERING SURVEYING & PLANNING

ONTARIO

368 SW 5TH AVE. 945 W. ONCOME
ONTARIO, OR 97914 HERMISTON, OR 97836
PHONE (541) 889-5411 PHONE (541) 567-2345
FAX (541) 889-2074 FAX (541) 567-2305
WEB: CK3LLC.NET

2-288 PAGE(S): 50-51

FIELDBOOK No.	0-288	PAGE(S):	50-51
DWG FILE No.:	B-1144		
FILENAME:	VO13043.DWG	JOB No.:	VO13043
DATE REVISED:		SHEET: 1	of 1
	DWG FILE No.: FILENAME:	DWG FILE No.: B-1144 FILENAME: VO13043.DWG	DWG FILE No.: B-1144 FILENAME: VO13043.DWG JOB No.: