
OREGON CORNER RESTORATION FORM

Section 30 Township 1N Range 32E County Umatilla Date: August 21, 2009 Condition Report Only Corner Designation: 1N32V5 Not found Remonumented Corner to sections 29, 30, 31, and 32, T1N, R32E, Unrecorded W.M., Umatilla County, Oregon. Surveyed in Referenced out

Previous Renewals / Surveys, etc.

Corner was originally set by Daniel Chaplin under contract No. 107 dated September 21, 1864. His record reads: Set stone, 20 x 12 x 8, for corner to secs. 29, 30, 31 and 32. David L. Haddock under survey 97-145-C states: Set railroad spike and three reference monuments.

Monument and Accessories found: (condition and source)
I found the railroad spike and references from 97-145-C in good condition.



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)
I removed the railroad spike and replaced it with a 2 1/2" brass cap on a 5/8" x 15" iron rod cemented into the asphalt. The cap is stamped as shown in the diagram above.

For references: I made no change to the references from 97-145-C.

The monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments Compass Declination Surveyors Seal NAD 83/1991 State Plane Coordinate Oregon North Zone REGISTERED N = 683,530.82 ift PROFESSIONAL Firm / Agency E = 8,625,239.25 ift LAND SURVEYOR Witness Tree Surveying Address RECEIVED BY: **Umatilla County Surveyor** P.O. Box G OREGON STEPHEN K. HADDOCK 6-10 Pilot Rock, Or. 97868 Date: Rec'd By: KK No. 10-93-C Party Chief Stephen K, Haddock

RENEWAL DATE 6-30-11