History of original corner establishment:

DIAGRAM

TIS R37E 830 829

A WOODEN POST 3'X 3 SQ.IN. 24" IN THE GROUND

15" PINE \$38W 27LKS. MKD. 48 BT 15" PINE \$57E 17LKS. MKD. 48 BT

17-5

Description of corner evidence found:

15" ROTTEN PINE STUMP \$38W 17.8' 15" ROTTEN PINE STUMP \$57E 11.2'

SCRIBING NOT VISIBLE. THESE TREES MATCH THE DESCRIPTION OF THE US FOREST SERVICE NOTES.

THERE IS A STONE SET BY RLS 645 APX. S68E 6.21 FROM THE CORNER

Description of monument and accessories I established to perpetuate the original location of this corner:

SET 2"x30" IRON PIPE WITH A BRASS-CAP MARKED:

TIS R37E 830 829 1978 RLS 346

14" FIR S67W 33.3' MKD. 4 S30 BT 8" FIR N74E 12.0' MKD. 4 S29 BT

THE BT'S HAVE BT SIGNS AND A RED PAINTED STRIPE. THE TWO NEW TREES HAVE A BRASS WASHER STAMPED RLS 346 NAILED TO THE LOWER BLAZE. THERE IS A 6' STEEL FENCE POST WITHIN 5' OF THE CORNER.

PROFESSIONAL LAND SURVEYOR OREGON MAY 6, 1955 WAYNE O. HARRIS

Form R6-7100-57 (9/71)

☆ GPO-798-276