PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/07/02

CORNER DESIGNATION: 2N32C9, the East Quarter Corner of Section 5.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors Corner Record: 88-19-C.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on galvanized iron pipe monument, 2.0 feet West of a railroad tie fence corner post with fences West and North, marked as shown in monument marking detail. Accessories reported on corner record are intact. Corner monument has two accessories.

MONUMENT MARKING DETAIL:

T2N R32E 1/4 S5 | S4 1988 PLS 1106

LOCATION & COMMENTS:

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 739029.82E = 8629347.86

FIRM/AGENCY: Will

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N32C9

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1777
WILLIAM R. WELLS
1106

renews 6-30402

Harry 05 26

ann A. Newms

RECEIVED BY

Umatilla County Sarras

Hac'd By

130 d 24 X 4 Q