	^	
	OREGON CORNER RESTORATION FORM	
	Section 15 Township 2N Range 32 EWM	
	County Umatilla Date 4/89	
	CORNER DESIGNATION Condition Report Only Not Found	
	Initial Point for Youngs 1st and X Renewed	
	2nd Additions to the City of Unrecorded Surveyed In	
	Pendleton - Also 1/4 corner between Sections 16-15 T2N R32 EWM Sections 16-15 T2N R32 EWM X Referenced Out	
	Previous Renewals/Surveys, etc.	_
		_
	Monument(s) & Accessories Found: (Condition and Source)	
	April, 1989 Initial Point for Youngs 1st and 2nd Additions to the City	_
	of Pendleton - Also 1/4 corner between Sections 16-15 T2N R32 EWM.	2234 m
	Existing 2" Iron Pipe apparently removed during construction of a	7
	new fence. This point is also the Initial Point for Blakey Addition to	
	the City of Pendleton	_
	the city of rendecon	7
10		-
	Chatab	-
	Monument Detail Sketch	1
	Set 5/8" Iron Pin with Young's Addition Young's 2nd Aluminum Cap attached	Add
	stamped "City of Pendleton"	
807	4   1   2	
	Pin Set	$\perp$
	S. W.	1
Yes	Blakey Addition	
10 Mars 10 M	Monument Set (Procedures and Description) S.W. Perkins	
	April 1989 Set new 5/8" X 24" Iron Pin with aluminum cap attached	
	stamped "City of Pendleton". Pin reset from original reference marks	
		_
	on file with the City of Pendleton.	_
		_
	New Accessories	
		_
		-
		_
		_
		-
	Location & Comments Surveyor's Sec	al
	Pin located at the S. W. Compass Declination	
	corner of Lot 12 Block 6 Firm/Agency City of REGISTERE	D
	PROFESSIO	NAL.
	the City of Pendleton Address 34 S. E. Dorion LAND SURVE	:YO
	51. 140	,
	Pendleton, OR 9/801	יה אינינו
		rde
	OREGON Party Chief Rick B OREGON	Residence
	Party Chief Rick B OREGON	Residence