PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, **DATE: 12/31/01**

CORNER DESIGNATION: 2N32, R-23, The North 1/4 Corner of Section 25.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished under Umatilla County Surveyor's Corner Record No. 93-054-C and accompanying Record of Survey.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap monument on galvanized iron pipe, buried 16" below ground in farmed field. Corner marked as shown in monument marking detail. Monument had been hooked with farm machinery and turned. Repositioned monument with cap readable from South and repacked dirt around it. As per Corner Record, accessories are intact. Corner has four accessories.

MONUMENT MARKING DETAIL:

T2N R32E S24 1/4 -----S25

1993

PLS 1106

LOCATION & COMMENTS:

Corner located in an active farmed field.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 720937.27

E = 8648273.73

FIRM/AGENCY: William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N32R23

REGISTERED PROFESSIONAL LAND SURVEYOR

JULY 22, 1977 WILLIAM R. WELLS

1106

renews 6-30-02

RECEIVED BY Umatilla County Same Rec'd Ey___