PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 10/05/01

CORNER DESIGNATION: 2N32V13, the Northeast Corner of Section 33.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Umatilla County Surveyors Corner Record: 94-109-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on galvanized iron pipe monument buried 8" below ground in good condition, marked as shown in monument marking detail.

Per corner record, all accessories are intact certificate everything exists and is fine except witness post sign on steel fence post 3 feet West is in poor shape.

MONUMENT MARKING DETAIL:

T2N R32E

S28 | S27

S33 | S34

1994

PLS 1106

LOCATION & COMMENTS:

Located on East side of McKay Creek on West edge of gravel drive. Access using road just North of bridge crossing McKay creek.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N: 715422.79

E:8635191.98

FIRM/AGENCY:

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N32V13

REGISTERED PROFESSIONAL LAND SURVEYOR

RECEIVED BY Juatilla County Survey

JULY 22, 1977

WILLIAM R. WELLS

renews 6-30-