PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/08/02

CORNER DESIGNATION: 2N33C21, The East Quarter Corner of Section 2.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors Corner Record: 92-29-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap in galvanized iron pipe monument with cap 8" above ground level, marked as shown in monument marking detail. Per corner record, all accessories are intact.

MONUMENT MARKING DETAIL:

T2N R33E 1/4 S2 | S1

PLS 1106

1992

LOCATION & COMMENTS:

Corner monument is located in small spring branch just South of a fence corner with fences North and East.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 740248.12E = 8676817.77

FIRM/AGENCY:

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N33C21

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 19/7
WILLIAM R. WELLS
1106

rencus 6-30-02

RECEIVED BY

Umaiilla County Surveyor

rare

Rea'd By

Na 02-43-9