

R-9

OREGON CORNER RESTORATION FORM

Section 29 Township 2N Range 33E

County Umatilla Date 8-18-94

R-9

CORNER DESIGNATION


- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_


Monument(s) & Accessories Found: (Condition and Source)

Found P-K nail set in survey No. 0-31-B and used in survey No. 89-50-B

Monument Detail



Sketch



Monument Set (Procedures and Description)

Set 2 1/2" brass cap on 1" G.I.P. 6" below the paving

New Accessories

- Alum. nail in power pole bears N17°29'E - 71.98 ft.
- Alum. nail in power pole bears N45°01'W - 38.07 ft.
- 3/4 x 36" rebar bears S35°35'W -31.55 ft.
- Alum. nail in R.R. tie fence post bears S1°59'E - 26.69 ft.

Alum nails are in brg. obj. signs & rebar is stamped RLS 1333 with yellow witness sign

Location & Comments

Surveyor's Seal

Corner is in middle of paved road

Compass Declination \_\_\_\_\_

Firm/Agency Don Staebler

RECEIVED BY

Umatilla County Surveyor

Date 8-24

By [Signature]

No. 945-110-A

Engr. - Surveyor

Address 1532 S. W. 41

Pendleton, OR 97801

Party Chief D. L. Staebler

Notes \_\_\_\_\_

Witness \_\_\_\_\_



*Donald L. Staebler*

OREGON  
SEPT. 23, 1977  
DONALD L. STAEBLER  
#1333