PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 11/15/01

CORNER DESIGNATION: 2N33, T-1, The West 1/4 Corner of Section 30 only.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished in 1988 Dependent Resurvey by BLM recorded in the Umatilla County Surveyor's Office.

MONUMENT AND ACCESSORIES FOUND:

Found a 3" brass cap on stainless steel monument, in monument box 14" below ground level, marked as shown in monument marking detail. Per BLM notes, the corner has 2 accessories. We did not dig up deep-1 magnet accessories.

MONUMENT MARKING DETAIL:

T2N R32E|R33E | 1/4 |S30 1988

LOCATION & COMMENTS:

Corner located approximately 4 feet West of West edge of Goad Road in farmed field. A field line on East side of road runs East.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 718439.08E = 8650961.90

FIRM/AGENCY: William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N33T1

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

Date 12-01
Bec'd By KK
Fig. 01-211-9