### PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 10/03/01

CORNER DESIGNATION: 2N33, T-5, The East 1/4 Corner of Section 30.

## PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was established on Record Survey No. 82-50-B.

## MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap buried 16" below ground, in good condition, marked as shown in monument marking detail. There is a steel fence post 0.2 feet East of Corner with top bent and flush with ground. Corner has no accessories.

#### MONUMENT MARKING DETAIL:

**T2N R33E** 

1/4

S30 | S29

1982

PLS 1106

#### **LOCATION & COMMENTS:**

Corner is approximately 2 feet East of East edge of gravel Road, (Pond Road). There is a field line running East from Corner.

# STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 718539.62E = 8656029.05

FIRM/AGENCY: William

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N33T5

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

matilla County 5.1.

Date 12-0/

New d By KE