## PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 10/03/01

CORNER DESIGNATION: 2N33, V-3, The South 1/4 Corner of section 30.

## PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most current record is Dependent Resurvey by BLM in 1988, recorded in the Umatilla County Surveyor's Office.

## MONUMENT AND ACCESSORIES FOUND:

Found a 3" brass cap on stainless steel pipe monument in an monument box, 8" below gravel road surface, in good condition marked as shown in monument marking detail. Found steel fence post with BLM tag wired to it stamped "T2N R33E SEC 31", 12 feet South of Corner. Did not search for buried deep-1 magnet accessories.

#### **MONUMENT MARKING DETAIL:**

**BLM** 

**T2N R33E** 

1/4 S30

S31

1988

### **LOCATION & COMMENTS:**

Corner is 2 feet South of centerline of Lloyd Road with field lines North and South.

# STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 715809.69E = 8653443.59

FIRM/AGENCY:

William R. Wells, PLS

P.O. Box 1696

Pendleton, Oregon 97801

\2N33V3

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Survey

Dale\_\_\_

300'd 3y 11-4