## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. A-1 History of original corner establishment: Record of the original survey DIAGRAM by Jacob C. Cooper, 1881, states: Set post, 5 ft. long, 6 ins. square, 2 ft. in the ground in heavy Fir timber and dense under-T2N growth sloping east for cor. to Twps. 1 and 2 N, R. 37 and 38 E. marked: T2N S31 on NE R37E 36 1 31 R38E R38E S6 on SE 1 6 T1N S1 on SW R37E S36 on NW with 6 notches on each edge, from which A Fir, 14 ins. diam. bears S47 $^{\circ}$ E43 lks. dist., marked T1N T1N R38E S6 BT, A Fir, 9 ins. diam. bears N200E 13 lks. dist. marked T2N R38E S31 BT, A Fir, 10 ins. diam. bears N 19°W 321ks. dist. marked T2N R37E S36 BT. A Fir, 10 ins. diam. bears N 19 321ks. dist. marked T2N R37E S36 BT.

A Fir, 10 ins. diam. bears S36 W 65 lks dist. marked T1N R37E S1 BT.

Record of the Resurvey of the E. Bdy. of T2N, R37E, by C. Campbell, 1901, states:
...At the corner of Tps. 1 and 2 N., R's. 37 and 38 E, which is a post, firmly set marked and witnessed as described by the Surveyor General with the exception of the NE and NW bearing trees which have entirely rotted away. I mark a Spruce, 16 ins.

Description of the NE and New Market C2N R38E S31 BT. A Larch, 10 ins. diam. bears N 85 W 32 lks. dist. marked T2N R37E S36 BT. <u>Description of Corner Evidence Found:</u> No trace remains of the original corner post. We establish the true corner point in the following relationship to the remains of the original and resurvey bearing trees: An orig. 10" Fir, now a 38" stump, we open and find good scribing "BT", bears S36°W 42.9 ft., And an orig. 14" Fir, now a stump hole, the tree is completely rotted away, bears  $544^{\circ}E$  28.4 ft. A resurvey BT, a 10" Larch, now a 28" White Fir, we open and find scribing "T2", bears  $N85^{O}W$  21.1 ft., And a resurvey BT, a 16" Spruce, now a 24" snag, 6 ft. tall, no marks or scars visible bears N  $60^{\circ}$ E 46.2 ft. No trace remains of the original NE and NW bearing trees. Description of monument and accessories I established to perpetuate the original location of this corner: At the true corner point, we set a 2"x30" galvanized Iron Pipe, 26" in the ground on a gentle E slope approx. 30 ft. N of a spring branch, with brass cap attached, marked: And mark the following new BT's: T 2N An 8" White Fir, scribed "T2N R38E S31 BT" on a double blaze S36 | S31 37 bears N470E 37.3 ft., S1 | S6 E E A 12" White Fir, scribed "T1N R38E S6 BT" on a double blaze T IN bears S710E 32.0 ft., PLS 1099 An 18" Spruce, scribed "TIN R37E S1 BT" on a double blaze bears S 1120W 42.6 ft., 1980 And a 12" Spruce, scribed "T2N R37E S36 BT" on a double blaze bears N 190W 38.2 ft. Attached brass washer stamped "LS 1099" to lower blaze of new BT's; Placed steel fencepost 5 ft. north of monument with sign 54-4 attached. Attached signs and painted BT's per Standard Specifications for Cadastral Survey, U.S.F.S. Region 6, Oct. 1979. I hereby certify the above described monument was established as herein described on Oct. 2, 1980 Witness: John Curtiss REGISTERED PROFESSIONAL Compass Declination: 20° East LAND SURVEYOR PREGON GARY L. LANGLITZ County Surveyor ...... County of. Umatilla

reby certify that the within instrument was filed in this office

(DEPUTY)

(COUNTY OFFICIAL)

David Frumber by Betty Shall