OREGON CORNER RESTORATION FORM Section 4 Township ЭN Range 28E County Umatilla Date: 06-19-02 Corner Designation: 3N28E11 Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out Previous Renewals / Surveys, etc. Survey S-14-B records setting a brass capped monument here. Survey S-119-B records finding that monument. Monument and Accessories Found: (condition and source) Found the record monument near an east west road. SKETCH DIAGRAM RR tie N16 °E T3N R28E 66.0 gravel road corner 😙 9 1981 PLS 933 MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None. REFERENCES SET: None. Made GPS tie to TRI Station Stanfield East Base. Latitude 45°45'45.32205" N Longitude 119°19'17.36313" W Oregon State Plane Coord. - North Zone Northing 766325.90 Easting 8502864.03 Ortho Height 661.50 NAD 83 (1991) Ellipsoidal Height 591.68 Location and Comments Compass Declination Surveyors Seal 20 °E From the junction of I84 and Highway 207, go south 1.6 miles. Take a field road east 0.8 miles. The corner is located south of a fence line. A REGISTERED PROFESSIONAL LAND SURVEYOR BO tag on a power pole witnesses the corner. David L. Haddock RECEIVED BY: Firm / Agency Date: _ 7-02 Haddock Surveying TREGON P. O. Box 1574 Pendleton, OR 97801 JULY 12, 1968 ID L. HADDOCK Rec'd By: DAVID L No. 02-

(541) -276-2174

RENEWS 6-30-03