OREGON CORNER RESTORATION FORM Section 10 Township Range 29E County Umatilla Date: 08/31/09 Corner Designation: 3N29E13 Condition Report Only Corner common to sections 3,4,9 and 10 T3NR29E. Not Found Remonumented Unrecorded Surveyed In Previous Renewals / Surveys, etc. Referenced Out Originally Surveyed by N.H. Gates in 1859. He set a post in a mound of earth. Zahner remonumented with a Granite rock 6"x13"x18" in private survey Book 1, Page 103. D. Haddock computed the location under survey 98-155-C. S. Haddock monumented w/ a 1 1/4" x 30" galvanized iron pipe w/ a 2 1/2" B.C. based on D. Haddock survey. Monuments and Accessories Found: (Condition and Source) Found A 2 1" B.C. Found a 5 Iron rebar w/opc #56295 lies S 9°30' E, 43.62'. Found a ½" Iron rebar w/rpc "DEA Control" lies N 42°15' E, 7.43'. Found a 5 Iron rebar w/opc #56295 lies N 81° E, 39.29'. Found an "X" cut into the southeast lifting eye of the irrigation pump lies N 66°30' W, 92.69'. Diagram Sketch **T3N R29E S4** , S3 S9 S10 B.C. 4" Deep 2008 56295LS 24" Deep NAD 83/91 OREGON STATE PLANE NORTH INTERNATIONAL FEET N766828.83 E8537972.74 LAT - 45° 45' 44.93562" N LON - 119° 11' 02.08063" W Monument (s) Set (Procedures and Description) None. References Set: None. **Location and Comments** Compass Declination Surveyors Seal The corner is .5 miles south of 17° E the intersection of Irwin Rd. and S. Ash Rd, on S. Ash Rd., and .5 REGISTERED miles east on a gravel road. **PROFESSIONAL** LAND SURVEYOR RECEIVED BY: Firm / Agency OREGON JANUARY II, 2005 ROBERT DOUGLAS ENGLISH Survey One, LLC. 43406LS Date: _/- // P.O. Box 382 Rec'd By: Pendleton, OR 97801 RENEWAL DATE: 12/31/09 (541) 276-2055