## OREGON CORNER RESTORATION FORM Section 7,8 Township Range 29E County Umatilla Date: 08/18/09 Corner Designation: 3N29G5 Condition Report Only 1/4 Corner common to sections 7 and 8, T3NR29E. Not Found Remonumented Unrecorded Surveyed In Referenced Out Previous Renewals / Surveys, etc. Originally Surveyed by N.H. Gates in 1859. He set a post in a mound of earth. Survey Q-511-Ax records finding a stone at this corner location. Monuments and Accessories Found: (Condition and Source) A stone. Diagram Sketch Echo Meadons Road Irrigation Ditch NAD 83/91 Stone OREGON STATE PLANE NORTH INTERNATIONAL FEET Steel Fence Posts Field Road N763941.42 E8527365.89 LAT - 45° 45' 18.11097" N LON - 119° 13' 32.320911" W Monument (s) Set (Procedures and Description) None. References Set: A §" x 30" Iron rebar w/ypc #43406 lies N 45°00' E, 40,03'. A 5" x 30" Iron rebar w/ypc #43406 lies S 30°00' W, 24.82'. A 8 x 30" Iron rebar w/ypc #43406 lies N 79°00' W, 3.52'. A 5 x 30" Iron rebar w/ypc #43406 lies S 53°00' W, 32.39'. Location and Comments **Compass Declination** Surveyors Seal The comer is .5 miles south of 17° F the intersection of Echo Meadows Road and Correa Lane. REGISTERED **PROFESSIONAL** LAND SURVEYOR Firm / Agency RECEIVED BY: OREGON JANUARY II, 2005 ROBERT DOUGLAS ENGLISH Survey One, LLC. P.O. Box 382 Date: 9-09 Rec'd By: Pendleton, OR 97801 RENEWAL DATE: 12/31/09 No. 09-147-K

(541) 276-2055