
## OREGON CORNER RESTORATION FORM

Section 9 **Township** 3N Range 29E County Umatilla Date: May 21, 1998 **Condition Report Only** Corner Designation: 3N29J13 Not found Remonumented Section corner common to sections 9, 10, 15, and 16, Unrecorded T3N, R29E, W.M. Surveyed in Referenced out

Previous Renewals / Surveys, etc.

Corner originally established by Gates in 1859 under contract No. 84 was a post in a mound of earth with charcoal. PE 5408 set a brass cap at the position of a found charred stake in a mound of stones in survey H-4-B.

Monument and Accessories found: (condition and source)
Found the brass cap set by Staebler in good condition in a mound of stones approximately five feet north of an existing fence corner.



## REFERENCES SET:

A 5/8" x 24" rebar with a 1 1/8" red plastic cap stamped ORLS 852 and WALS 13922 bears N89°30'52"W, 35.58 feet under the existing fence.
A 5/8" x 24" rebar with a 1 1/8" red plastic cap stamped ORLS 852 and WALS 13922 bears N89°48'50"W, 70.99 feet under the existing fence.
A 5/8" x 24" rebar with a 1 1/8" red plastic cap stamped ORLS 852 and WALS 13922 bears S1°06'01"E, 61.88 feet under the existing fence.
A 5/8" x 24" rebar with a 1 1/8" red plastic cap stamped ORLS 852 and WALS 13922 bears S1°57'57"E, 32.09 feet under the existing fence.

Location and comments	Compass Declination	Surveyors Seal
RECEIVED BY: Umatilla County Surveyor Date: 8-98 Rec'd By: KK No. 98-/55-C	Firm / Agency Haddock Surveying Address P.O. Box 1574 Pendleton, Or. 97801 Party Chief Stephen K, Haddock	REGISTERED PROFESSIONAL LAND SURVEYOR  OREGON JULY 12, 1868 DAVID L. HADDOCK 852 RECEIVED BY  Umatille County Surveyor
		a Date

Rag'd By\_\_\_\_