OREGON CORNER RESTORATI	ON FORM	
County Umatilla Date:	Ownship 3N 03/08/10	Range 29E
Corner Designation: 3N29R5		
Corner common to sections 19,20,29,30	T3NR20F	Condition Board Oak
10,20,20,00	75111232.	Condition Report Onl
		XRemonumented
		UnrecordedXSurveyed In
		XReferenced Out
Previous Renewals / Surveys, etc.		
Originally Surveyed by Gates. He set a po	ost in a mound of earth in 1860.	
Stebler set a 2 ½" Brass cap in 1974, Sur Edwards found Brass capped monument	vey #I-158-B.	
zamarao louna brass capped monument	badiy bent, 91-92-R.	
Monuments and Accessories Found: (0 Found Brass cap with bent Iron pipe as cap	Condition and Source) Alled by Edwards.Top half was I	badly bent out of position.
Diagram		
Diagram		Sketch
T3N R29E	€	
S19 S20		
S30 S29	-	
PLS43406LS	3.0	•
2010		2 1/2" BC
		Control various and
NAD 83/91		0
OREGON STATE PLANE NORTH		
INTERNATIONAL FEET	•	•
N750739.16		
E8527596.56		
LAT - 45° 43' 07.74112211" N		
LON - 119° 13' 31.99836177" W		
Monument (s) Set (Procedures and De	scription)	
Set a 1 1/8" x 30" Galvanized iron pipe with	a 2 ½" Brass cap, stamped as	s shown above, in place of
the found bent monument. Monument is	18" below surface.	
Poforonoso Cata "Doon One" manuals by	. D1	
References Set: "Deep One" magnets by An Orange magnet, 18" deep lies N 39°18		
A Silver magnet, 18" deep lies N 65° E, 20	0.22'.	
A Pink magnet, 18" deep lies S 32°20' E,		
A Blue magnet, 18" deep lies S 40°30' W,	23.37'.	
ocation and Comments	Compact Deallers	
The corner is 1.2 miles South of the	Compass Declination 17° E	Surveyors Seal
ntersection of Hwy. 320 and Snow Road, and West 0.5 miles from the Ag. Runway.		
		REGISTERED
		PROFESSIONAL LAND SURVEYOR
		A A O
		Total Eyligh
DEGETTED DV	Firm I A	2000 2 - 17
RECEIVED BY:	Firm / Agency	OREGON JANUARY II, 2005
RECEIVED BY:	Survey One, LLC.	OREGON JANUARY II, 2005 ROBERT DOUGLAS ENGLISH 45406LS
Date: 3-10 Rec'd By: KK		ROBERT DOUGLAS ENGLISH