OREGON CORN Section 19,20,29 County Umatilla		wnship 3N	Range 29E
	OTT STEERS	03/08/10	Ç)
Corner Designation	: 3N29R5		
Corner common to se	ections 19,20,29,30 T	3NR29E.	Condition Report Or X Not Found X Remonumented Unrecorded X Surveyed In X Referenced Out
Previous Renewals	/ Surveys, etc.		
Originally Surveyed to Stebler set a 2 ½" Br Edwards found Brass	y Gates. He set a po	est in a mound of earth in 18 vey #I-158-B. badly bent, 91-92-R.	60.
Monuments and Ac	cessories Found: (0	Condition and Source)	
Found Brass cap with	bent Iron pipe as ca	illed by Edwards. Top half wa	as badly bent out of position.
Diagram T3N R29E	ENI	<u>a</u>	Sketch
/ ION IZSE	1		
S19 S20 S30 S29			
PLS43406LS 2010			
			2 1/2" BC
1140 0004			0
NAD 83/91 OREGON STATE INTERNATIONAL			
N750734.33 E8527601.89			
LAT - 45° 43' 07.69 LON - 119° 13' 31.9			
Monument (s) Set (Set a 1 1/4" x 30" ga the found bent monu	lvanized iron pipe wit	th a 2 1/3" brass cap, stampe	d as shown above, in place of
References Set: "Do An Orange magnet," A Silver magnet, 18" A Pink magnet, 18" A Blue magnet, 18"	8" deep lies N 39°13 deep lies N 65° E, 2 deep lies S 32°20' E,	5' W, 18.23'. 0.22'. 27.08'.	
Location and Comm The corner is 1.2 mile	s South of the	Compass Declination 17° E	Surveyors Seal
intersection of Hwy. 3 and West 0.5 miles fro			REGISTERED PROFESSIONAL LAND SURVEYOR
		- 1 <u></u> -	Kotate D. English
Survey One, LLC		Survey One, LLC.	OREGON JANUARY II, 2005 ROBERT DOUGLAS ENGLISH 43406LS
Date:/_// Rec'd By:// No// -(2-		P.O. Box 382 Pendleton, OR 9780 (541) 276-2055	RENEWAL DATE: 12/31/II