(*)		
OREGON CORNER RESTORATION	FORM	
Section 29,30 Township	3N	Range 29E
County Umatilla Date:	03/08/10	
Corner Designation: 3N29T5		
1/2 Corner common to sections 29,30 T3NR298		Condition Report Only
		XNot Found Remonumented
		Kernonumented Unrecorded
		X Surveyed In
		XReferenced Out
Previous Renewals / Surveys, etc.		
Originally Surveyed by Gates, set a post in a n	nound of earth, 1859.	
Harris set a ½" Iron rebar in survey #Q-1655.		
Monuments and Accessories Found: (Cond	lition and O	
None.	iluon and Source)	
Diagram		
Diagram		Sketch
T3N R29E		
/ 1/4		•
S30 S29	200000000000000000	
	•	
PLS43406LS	Pivot Pad	O 2 1/2" BC
2010	rau	
2010		
		•
NAD 93/04		
NAD 83/91 OREGON STATE PLANE NORTH		
INTERNATIONAL FEET		
2017/19/2007 PC 278		
N748054.51		
E8527650.53		
LAT - 45° 42' 41.23032626" N		
LON - 119° 13' 31.83466527" W		
Manument (a) Set (December 2011)		
Monument (s) Set (Procedures and Description) Set a 1 1/8" x 30" galvanized Iron pipe with a 2 1/2" Brass cap, stamped as shown above.		
Set by single proportion between found monur	nents North and South on	s snown above. he half mile
		Time.
References Set:		
A Silver magnet, 18" deep lies N 45°40' E, 16.3 A Pink magnet, 18" deep lies S 16°20' E, 17.19	4'. "Deep One" magnets	s by Bernsten.
A %" x 30" Iron rebar w/rpc# 43406 lies S 63°50' W, 20.44'.		
A %" x 30" Iron rebar w/rpc #43406 lies N 81° V	V. 18.99'.	
■ CONTROL OF A CO		
Location and Comments Co	ompass Declination	Surveyors Seal
The corner is 1.5 miles South of the intersection of Hwy. 320 and	17° E	<u> </u>
Whitehouse Road, then East on a gravel road		DECISTEDED
1.0 mile.		REGISTERED PROFESSIONAL
		LAND SURVEYOR
		1.10
	_	Frontal. Eyler
RECEIVED BY:	Firm / Agency	OREGON JANUARY W, 2005
	Survey One, LLC.	ROBERT DOUGLAS ENGLISH
Date: \$-/0	P.O. Box 382	43406LS
Rec'd By: KK	Pendleton, OR 97801	RENEWAL DATE: 12/31/II
No. 10-40-R	(541) 276-2055	