OREGON CORNER RESTORATION FORM					
Section		Township		Banna 20F	
County	Umatilla	Date:	03/08/10	Range 29E	
Corner Designation: 3N29T5					
1/4 Corne	r common to sections	29,30 T3NR2	9E	x xx	Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out
Previous Renewals / Surveys, etc. Originally Surveyed by Gates, set a post in a mound of earth, 1859. Harris set a ½" Iron rebar in survey #Q-1655.					
Monume None.	ents and Accessories	Found: (Cor	ndition and Source)		
	)iagram			Sketch	
	73N R29E				
S30	1/4 529 \$43406LS 2010		Pivot Pad	O 2 ½" BC	•
	ON STATE PLANE NO IATIONAL FEET 9.68	RTH	*		
	5° 42' 41.18664" N 19° 13' 31.76774" W				
Monument (s) Set (Procedures and Description)  Set a 1 1/4" x 30" galvanized iron pipe with a 2 ½" brass cap, 22" below surface, stamped as shown above. Set by single proportion between found monuments North and South one half mile.					
A Silver I A Pink m A 5/8" x 3/	ces Set: "Deep One" r magnet, 18" deep lies agnet, 18" deep lies S D" Iron rebar w/rpc# 43 D" Iron rebar w/rpc #43	N 45°40' E, 16 16°20' E, 17. 3406 lies S 63°	3.34'. 19'. °50' W, 20.44'.		
The com	and Comments er is 1.5 miles South of the ection of Hwy. 320 and	f '	Compass Declination 17° E	Surve	yors Seal
	ise Road, then East of		ı	PROFI	STERED ESSIONAL SURVEYOR
RECE	EIVED BY:		Firm / Agency Survey One, LLC.	ROBERT DO	EGON ARY 11, 2005 UGLAS ENGLISH
Rec'd	1-11 By: KK 11-18-R	_	P.O. Box 382 Pendleton, OR 97801 (541) 276-2055		DATE: 12/31/II