EXITIFIED RECORD OF LAND CORNER MONUMENTATION

3N, R 34E., W.M.

History of original corner establishment:

The most recent record of GLO establishment indicates this corner was established by Currin and Noland, U.S. Deputy Surveyors, in 1887. The record states:

No record of surveys by C.E. Redfield, U.S. Indian Service Surveyor, were found in the Umatilla Agency records.

Corner Code No. N-17 Note: Monument marked as shown below

DIAGRAM

T3N R34E S151S14

9221923 1992

PLS 1106

Compass Declination: 18.0°

Description of corner evidence found:

Found 4 way road intersection. After confirming the road intersection by survey, I re-establish the corner at the intersection of the 4 way road intersection. See Survey No. 92-26-B.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2 1/2" brass cap on a 1 1/4" by 30" G.I.P. 36" in ground at intersection of North-South, East-West dirt roads from which:

A 5/8" by 30" rebar bears N 42 1/2°E - 33.26' dist. with a steel fence post 1 foot away with a Bearing Object sign attached. A 5/8" by 30" rebar bears S 59°E - 42.66' dist. with a steel fence post 1 foot away with a Bearing Object sign attached. A 5/8" by 30" rebar bears S 62°W - 36.71' dist. with a steel fence post 1 foot away with a Bearing Object sign attached. A 5/8" by 30" rebar bears N 1/2°W - 48.36' dist. in C/L of dirt road.

Each reference corner rebar is capped with a yellow plastic cap marked "W.R. Wells, PLS 1106".

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of County of State of, I hereby certify that the within instrument was filed in this office for record on the...... day of....... , 19..... RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor

aPO-798-276

Rec'd Dy___