ON PUBLIC LAND CORNER REPORT / RESTORATION REPORT / Umatilla County Surveyor's Office

SECTION	TOWNSHIP		RANGE	_		
19 and 20				te pod Markovita		
unu zu	3N 36E		30E	36E		
			152			
COUNTY:					DATE	
Umatilla				6/20/08		
CORNER DESIGNATION: P-5				(Please check one)		
			-	Ø	Condition Report Only	
1/4 Corner common to Section	ns 19 and 20		-	=	Not Found	
			-	늗	Renewed	
			-	ᇹ	Unrecorded	
3			-	_	Surveyed In	
			-	=	Referenced Out	
Previous Renewals / Surveys, etc.				=	recipioda out	
Corner was originally set by U.S. Deputy Surveyors, J.P. Currin and J.E. Noland, under contract dated, May 4, 1887. The Deputy Surveyors notes state "Set a Basalt Stone 18x10x8 ins., marked ¼ on the W. face with a mound of stone over it". U.S. Indian Services Surveyor, C.E. Redfield found the Original monument in 1919 and set an Iron Post in its place.						
Monument(s) & Accessories Found: (Condition & Source)						
Found a 2" Galvanized Iron Pipe with a 2 ½" Brass Cap, protruding 12", in good condition, solidly set on an open South facing slope.						
Monument Detail:		Sketch:		_		
INDIAN ALLOTY 1/4 S- 1/4 S- 1/3 R-31 1/9 1/9 Monument Set (Procedures and	19 20 E	1			NEID EDICK X OIDFONCE	
Location & Comments:			- 1	Co	empass Declination:	
Monument is located on a steep, open South slope, 200 feet ± South of a field edge and 150 feet ± South of an old Fence						
Firm / Agency				S	URVEYOR'S SEAL	
USKH		- 1				
Address: 5 N. Colville St., Wall	a Walla, Wa 99632	1				
Party Chief Greg E. Flowers		7			REGISTERED PROFESSIONAL LAND SURVEYOR	
Notes			۲	1	OREGON JUNE 30, 1997	
Witness		1	- 1		GREG E. FLOWERS	
Damon Locke			`	_	02820LS RENEWS 12/3/109	
					RENEWS (7/3/10)	