OREGON CORNER RESTORATION FORM

SECTION 21,28 TOWNSHIP 4 NORTH RANGE 28 EAST

R-11

COUNTY: UMATILLA

DATE AUG/21

CORNER DESIGNATION

1/4 CORNER

X CONDITION REPORT ONLY

NOT FOUND
RENEWED
UNCOVERED


__SURVEYED_IN __REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

SURVEYED IN 1860 BY HAFT. SURVEYED IN 1971 BY THOMPSON. LS 951 RESET THIS MONUMENT IN 1986 BY SINGLE PROPORTION. SEE RECORD OF SURVEY 92-045-C.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

I RECOVERED THE CORNER AND COMPARED ITS LOCATION WITH DUAL MONUMENTATION IN THE AREA AS REQUESTED. PLEASE REFER TO TO RECORD OF SURVEY THAT WAS RECORDED ALONG WITH THIS CORNER RESTORATION FORM FOR MY ANALYSES. THE ACCESSORIES FOR THE CORNER WERE NOT RECOVERED DURING THIS SURVEY DUE TO THE FACT IT HAD NO BEARING ON THE CORNERS LOCATION. PLEASE REFER TO SURVEY NUMBER 19-080-C AND THE CORNER RESTORATION FORMS RECORDED WITH SAID RECORD OF SURVEY FOR ACCESSORY INFORMATION.



NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

FROM INTERSECTION OF BUTTER CREEK HIGHWAY AND FEEDVILLE ROAD GO WESTERLY ±400 FEET TO THE CORNER.

FIRM/AGENCY
PRIMM LAND SURVEYING, INC.
P.O. BOX 1322
HERMISTON, OREGON 97838

LAND SURVEYOR BRIT L. PRIMM

WITNESS KEITH P. PRIMM SURVEYOR'S SEAL

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 13, 1999 BRIT L. PRIMM 48509

EXPIRATION DATE: 12/31/22