## OREGON CORNER RESTORATION FORM Section County 3 Township NE Range 28E Umatilla 06-14-02 Date: Corner Designation: 3N28A15 Condition Report Only Not Found Remonumented Unrecorded Surveyed In Referenced Out Previous Renewals / Surveys, etc. Corner was set by survey S-156-C. Monument and Accessories Found: (condition and source) Found a brass capped monument as described below. ◆ COR. SKETCH DIAGRAM 6" x 6" sage stump at top of road cut \$29°24'E 69.5' with BO tag. 0 T4N R2BE canal road 534 1/4 -S3 ditch T3NR28E 1980 **PLS933** MONUMENT (S) AND ACCESSORIES SET (Procedures and Description) None REFERENCES SET: None. Made GPS tie to TRI Station Stanfield East Base. Latitude 45°46'37.80722"N Longitude 119°18'02.32371"W Oregon State Plane Coord. — North Zone Northing 771719.72 Easting 8508104.34 NAD 83 (1991) Ortho Height 621.26 Ellipsoidal Height 551.42 Location and Comments Compass Declination Surveyors Seal From the junction of I84 and Highway 207, go south 0.6 miles. Take a road through a stock yard east 0.1 mile and follow the road along the northerly side of an irrigation ditch northeasterly. Follow this road 1.8 miles. The corner location id marked by a BO sign on a sage stump at the top of a small cut. REGISTERED PROFESSIONAL LAND SURVEYOR RECEIVED BY: David L. Haddock Firm / Agency OREGON JULY 12, 1968 DAVID L. HADDOCK 852 Haddock Surveying P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174 Rec'd By: No. \_\_ RENEWS 6-30-03